

# Easy Clean Instructions

1. Shut off the gas (CO2 or Nitrogen) of the beer line you want to clean.
2. Move the keg connector from the keg to the cleaning connector.
3. Open the Water shutoff (Vesi) valve.
4. Turn the three-way valve to the Cleaning (Pesu) position.
5. Bleed the air out from the fob detector.
6. Pour beer from the tap until it turns clear (beer -> detergent).
  - a) Let the detergent work for 15 minutes.
  - b) Pour detergent from the tap, if it is gray, let it work again another 10 minutes. Repeat until it turns clear.
7. Turn the three-way valve to the Rinse (Huuhtelu) position.
8. Bleed the air out from the fob detector.
9. Pour from the tap until the detergent turns into water (at least 5 liters, twice the tubing length).
10. Close the water shutoff of the washing system.
11. Disconnect the keg connector from the cleaning connector.
12. Open the operating pressure of the beer lines (CO2 or Nitrogen).
13. Let off the gas from the keg connector by pressing the handle slightly.
14. Connect the keg connector into the keg and bleed the air out from the fob detector.
15. Pour water from the tap until the it turns into beer.

DONE!